

N 38th St - Gus Young Ave Area Rehabilitation Project

City-Parish # TBD, PDP SGC-R-0004

Project Start: **3rd Quarter 2014**
 Advertise for Bids: **4th Quarter 2015**
 Anticipated Project End: **1st Quarter 2017**


Rehabilitation of the sewer collection system is a comprehensive physical process that begins with cleaning and inspection of sewer pipes and manholes. Typical rehabilitation repairs include pipe and manhole replacement and trenchless technologies that minimize above ground disturbances, such as cured-in-place pipe liners.



One of the first steps in rehabilitation includes a physical inspection of manholes and pipes to identify blockages.



Simply cleaning the pipes and manholes in preparation for the physical inspection removes blockages, debris and roots.



N 38th St - Gus Young Ave Area Rehabilitation Project Facts

For this project:

- Approximately 85,021 linear feet of pipeline to be inspected and rehabilitated
- Approximately 340 manholes to be rehabilitated or replaced

Design Consultant:

Rehab Prog Mgmt Team

Construction Contractor:

To be determined

Estimated Construction Cost: \$3.6 M